


# K3 KIT ASSEMBLY MANUAL ERRATA

Rev. M-1, January 11, 2015

## MAKE THESE CHANGES TO YOUR MANUAL BEFORE STARTING INVENTORY AND ASSEMBLY


A new synthesizer pc board is now being shipped for your K3. The following changes are required to install the new board. The new and original synthesizer boards are shown below:



**Page 52:** Delete the first step and figure 72. The stiffener is not used on the new KSYN3A board.

**Page 53:** The new KSYN3 synthesizer is installed exactly as shown for the previous synthesizer.

**Page 54, Figure 76:** The location of J83 is different on the KSYN3A board. It is closer to the KREF3 board as shown in the diagram below:



**Page A-5 (Parts List):** The “New KSYN3A Synthesizer” image above replaces the synthesizer shown. Change the part number of the synthesizer to E850638.

**K3 Owner’s Manual:** The Synthesizer Calibration Procedure described on page 49 of your K3 Owner’s Manual is no longer applicable.