

KRX3A SUB RECEIVER INSTALLATION AND OPERATION MANUAL ERRATA

Rev. H1-1, December 23, 2016

MAKE THESE CORRECTIONS TO YOUR REV H1 MANUAL OR ANNOTATE YOUR MANUAL TO REFER TO THIS ERRATA AT THE PLACES INDICATED

- Page 43, Figure 47:** Replace the figure with the following which corrects the connection of the TMP cable from a K144XV with the External Phase Lock option to J1 of the Main KSYN3A.

