

P3 OWNER'S MANUAL ERRATA

Rev. E-1, September 15, 2015

E740152E

MAKE THESE CHANGES TO YOUR REV E1 MANUAL

1. **Page 12:** At the end of the paragraph starting "RS232 PC is a female..." add the following or insert a note to refer to this errata when connecting the P3 to your K3S.

The RS232 cable used with a K3S has an RJ45 connector at one end instead of the DE9 connector used with a K3. When plugging the RJ45 connector into the K3S rear panel be sure it is fully seated. The rubber boot around the connector may press against the rear panel and give you the feeling it is seated but the latch has not engaged. If not fully seated so the latch engages communications will not occur between the P3 and the K3S. One symptom is that the K3S frequency information will not appear on the K3S display.