

KAT1 MANUAL ERRATA

March 10, 2003 (rev. C-1)

**YOU MUST MAKE THESE MANUAL CORRECTIONS
BEFORE YOU BEGIN ASSEMBLY OR YOUR
KAT1 WILL NOT OPERATE CORRECTLY**

1. **Page 2, Parts Inventory:** U1 may be a PIC16F872, PIC16F872A, or PICC72A microcontroller.
2. **Page 7, K1 RF Board Preparation, 2nd step (middle of the page):** If your K1's RF board is revision E or later, you will not need to solder or unsolder R36 as was necessary with older K1 RF boards. Instead, this step should read: "Move the RF DET jumper (on 3-pin header P3) to the 'KAT1' position." (If you need to remove the KAT1 later to align a new Filter board, you'll need to move P3 back to the 'K1' position.)