

P3 OWNER'S MANUAL REV A4 TO A5 CHANGES

September 4, 2010

1. Incorporated outstanding errata A3-1
2. Expanded text on Menu to clarify the key and knob operation (pg 12).
3. Corrected reference to J102 – should have been J901 – on pg 36.
4. Added front panel board handling instructions to avoid damage to the transformers to the assembly procedure, parts list, and servicing instructions (pgs 26, 29, 40)
5. Added instructions for downloading firmware to the K3 with the P3 in the RS232 path (pg 13).
6. Added instructions for recovering from a K3 hung in bootstrap mode because the P3 was turned on while attempting a download to the K3 (pg 13).
7. Clarified instructions for configuring the P3 power switch operation (pg 18).