XV432 ASSEMBLY MANUAL ERRATA

Rev. C-7, March 27, 2011

MAKE THESE CORRECTIONS TO YOUR MANUAL BEFORE YOU BEGIN ASSEMBLY.

- **1. Page 8, Parts Inventory, Third from Bottom:** Add new part: Quantity 1, Description DB-15 Male Connector (mates with ACC connector on K3), Part # E620161
- 2. Page 8, Parts Inventory, Second from Bottom: Change the quantity of the DB-9 Back Shell from 1 to 2.
- **3.** Page **8, Parts Inventory, Bottom (Y1):** Change the description to read "Crystal, 134.667 MHz 5th Overtone, HC-43/U" and change the part number to "E660045"
- **4.** Page 11, Parts Inventory: Add the following new parts at the bottom of the page:

Quantity	Description	Elecraft Part Number				
1	Resistor, 1/4 watt, 5%, 10 ohm (brn-blk-blk)	E500054				
2	Capacitor, monolithic, 0.1 uF (104),50V,20%,0.1" lead spacing	E530020				
1	Capacitor, electrolytic, 10 uF,16V,20%, 0.1" lead spacing	E530142				

Note: The above added parts do not have reference designators.

- 5. Page 12, Parts List, Row 18 (Elecraft Part Number E530215): Delete C7 and change the QTY to 5.
- 6. Page 12, Part List, Row 15, (Elecraft Part Number E530120): Add C7 and change the QTY to 22.
- 7. Page 13, Parts List, L19: Change the description to read "Inductor 86-104 nH 7mm, Yellow, Variable" and change the part number to "E690165".
- **8.** Page 36, Figure 36: Near the center of the drawing, change "K9" to "K10".
- 9. Page 39, Right Column: Insert before the last step, "See attached page". Attach the following to the manual.

L	Bend	the RF	power	module	lead at	ove the	pad le	eading	o C27	up awa	y from	the s	older p	oad.	This is	s the	lead at
the	e right i	n Figur	e 40.														

ĺ		Solder the remaining	three RF now	ver module leads	directly to the pads
Į,	_	bolder the remaining	unce iti pow	ci inoduic icads	uncerty to the paus.

Solder one end of the 10 ohm (brn-blk-blk) 1/4 watt resistor to the pad for the remaining lead and solder the free end of the resistor to the RF power amplifier module as shown below. Keep the leads short.



Turn to the XV Transverter Builder's Alert: Bypass Capacitor Change supplied with your kit and install the bypass capacitors per those instructions. The capacitors are included in your kit.

- 10. Page 10, Parts Inventory: In description for Q1, change "(MPS918)" to "(NTE108)".
- 11. Page 29, Left Column, First Step: Change the description of L19 to "yellow body."
- 12. Page 31, Left Column, Last Step: Change "MPS918" to "NTE108".