

Manual Supplement

Manual Title:	45 Service	Supplement Issue:	1
Part Number:	609203	Issue Date:	12/00
Print Date:	March 1999	Page Count:	1
Revision/Date:			

This supplement contains information necessary to ensure the accuracy of the above manual. Enter the corrections in the manual if either one of the following conditions exist:

1. The revision letter stamped on the indicated PCA is equal to or higher than that given with each change.
2. No revision letter is indicated at the beginning of the change.

Change #1

On page 6-5, Table 6-2, replace MP2 and MP3 with the following, and add MP23.

MP	2	PAD TRANSFER, WINDOW	835496	1
MP	3	ASSEMBLY CHASSIS	784793	1
MP	23	CALIBRATION SEAL	735274	1