

WARNING

TO AVOID ELECTRIC SHOCK AND OTHER HAZARDS, FLOAT 30V MAX AND OBSERVE SAFETY PRECAUTIONS OF UNIT UNDER TEST

STATUS LINES

BIT	FUNCTION
7	PWR FAIL
6	—
5	—
4	**RESET
3	IREQ
2	NMI
1	—
0	**RDY

CONTROL LINES

BIT	FUNCTION
7	—
6	—
5	—
4	R/W
3	—
2	—
1	—
0	*SYNC

**FORCING LINES

*USER WRITEABLE

PIN ASSIGNMENTS

