

CUSTOMER SUPPORT**SSU-05352-3**160994
4822 872 09442

Related to: ScopeMeter®
 Models 93-95-97
 Service Manual 4822 872 05352

Already published: SSU-05352-1, SSU-05352-1

CLASS 3

Subject: - Modification on SSU-05352-2

The part location on the new A1 PCB is not according to the documentation. The following pages are numbered in the same way as the ones of SSU-05352-2. In the following description you can see how you should update your documentation.

| Page number to replace | Instruction |
|------------------------|--|
| 10a - 3a | Insert the new page and scratch the old page 10a - 3a, or modify the old page. The modification are printed in bold. |
| 10a - 5a/6a | Replace this page. |

CLASS 3

Subject: - Modification on Service Manual

The part location on the old A1 PCB is not according to the documentation. The following pages are numbered in the same way as the ones of Service Manual. In the following description you can see how you should update your documentation.

| Page number to replace | Instruction |
|------------------------|---|
| 10 - 3 | Insert the new page 10 - 3 (A1) Scratch the location list on the old page 10 - 3 |
| 10 - 5 / 10 - 6 | Replace this page by the new 10 - 5 / 10 - 6 |
| 10 - 7 / 10 - 8 | Replace this page by the new 10 - 7 / 10 - 8. Only 10 - 8 is modified. |
| 10 - 9 / 10 - 10 | Replace this page by the new 10 - 9 / 10 - 10. Only 10 - 10 is modified. |