

Page 4-16 Meter Part table

Modify the table steps 2,3, and 4:

Step	SIGNAL SOURCE	SIGNAL AMPL / FREQ	TEST TOOL INPUTS	REQUIRED
2	Fluke 5100B	300 mV / DC 3V / DC	banana	298.0...302.0 mV 2.980...3.020V
3	Shorted Input Fluke 5100B	0.0Ω 100.0Ω 1.0 kΩ 10 kΩ 100 kΩ 1 MΩ 10 MΩ	banana	000.0Ω...000.5Ω 099.0Ω...101.0Ω 0.990 kΩ...1.010 kΩ 09.99 kΩ...10.10 kΩ 099.0 kΩ...101.0 kΩ 0.990 MΩ...1.010 MΩ 09.90 MΩ...10.10 MΩ
4	Fluke 5100B	1.0 VDC	banana	0.990...1.010V

Section 5.2 RECOMMENDED CALIBRATION ADJUSTMENT EQUIPMENT

Replace the third sentence “The ScopeMeter can be used immediately: there is no warm-up time specified” by “Allow the ScopeMeter to warm up for at least 20 minutes”.

Section 9 REPLACEABLE PARTS LIST

Page 9-2 Table 9.1 add:

Item	Figure	Description	Ordering code	Qty
38	9.1	Bottom screening A2	5322 466 83171	1

Page 9-3 Figure 9.1 add item number 38 to BOTTOM SCREENING A2