

Legend

Ctrl+ with the Control key
Alt+ with the Alt key
Shift+ with the Shift key

MET/TRACK

F1 Help
Ctrl+S Save

Adding Records

F2 Add Inventory
F3 Add Calibration
F4 Add Location
F5 Add Maintenance
F6 Add Customer

Editing Records

Shift+F2 Edit Inventory
Shift+F3 Edit Calibration
Shift+F4 Edit Location
Shift+F5 Edit Maintenance/
Repair
Shift+F6 Edit Customer
F7 Edit Validation
Ctrl+M Edit Merge

General Functions

Ctrl+F12 Assign Asset to a
customer
Ctrl+L Log-on as a new
user
Ctrl+O Log-off
Ctrl+D Select a new
desktop
Ctrl+F Search

Accessing other Applications

Ctrl+R Met/Cal Runtime
Ctrl+E Met/Cal Editor
Ctrl+Q Quick Reports

MET/CAL Editor

F1 Help

File Commands

Ctrl+N New
Ctrl+O Open Procedure
Ctrl+S Save Procedure
Alt+S Save to Default
Directory
Ctrl+D Change Default
Directory
Ctrl+F Open Text File
Ctrl+J Save Text File
Ctrl+F4 Close
Ctrl+P Print
Alt+F4 Exit

Edit Commands

Ctrl+X Cut
Ctrl+C Copy
Ctrl+W Copy to
Ctrl+V Paste
Ctrl+G Insert File
Del Delete
Alt+F3 Find
F3 Find Next
Ctrl+F3 Replace
Ctrl+A Adjust
Ctrl+Enter Break
F6 Continue
Ctrl+I Name Procedure

Compile Commands

F8 Check Line
F9 Next Error
Shift+F9 Previous Error
Ctrl+F9 Re-warn
Ctrl+T TUR Report

Test Run Commands

F2 Restart
Alt+F2 Go
Ctrl+F2 Show

Configure

Ctrl+M Text Mode Toggle
F12 Instruments