



Mounting Instruction

Plug S150 + Cable RG11


- 1) Prepare the cable




- 2) Solder the center conductor
Tin-plate the screen on the front end




- 3) Push the plug parts as follows to the cable




- 4) Connect the screen with the connector case via a soldering eyelet



5) Final mounting




6) Push all together and screw it together



This mounting instruction is logical also valid for connectors of the same construction e.g. HVS 65. The difference is only the length of the plug and the cable diameter.

Valid for HVS 65 "L" = 239 mm Total length of the plug "S" = 289 mm

**Information about the place need on the
equipment rear side
Plug S150 + Cable RG11**



Bending radius for other cables
C 2124
C 2121

single
150 mm
220 mm

repeated
approx. x 4
approx. x 4