

G1000[™]

*audio panel pilot's guide
supplement for the Diamond DA40*

Record of Revisions

Revision	Date of Revision	Revision Page Range	Description
A	02/14/05	6B-1	Initial release.

This document is only intended to highlight G1000 Audio Panel (GMA 1347) information that is specific to the Diamond DA40 aircraft and it supersedes related information presented in the G1000 Audio Panel Pilot's Guide.



NOTE: For a description of the GMA 1347 as well as details as to its operation, please see the *Garmin G1000 Audio Panel Pilot's Guide*.

HEADSET JACKS & KEYED ICS OPERATION

The Diamond DA40 is equipped with four (4) stereo headset jacks (for the pilot, copilot and two passengers).

Keyed ICS operation is not available on the Diamond DA40.

TRANSCEIVERS

The Diamond DA40 is not factory-equipped with COM3 MIC, COM3 and TEL capability. On the Diamond DA40, if COM3 or TEL is disabled on the GMA Configuration Page of the PFD, pressing the **COM3 MIC**, **COM3**, or **TEL** key, respectively, does not illuminate the corresponding annunciator light.



NOTE: The use of split COM (**COM 1/2** key) is not recommended in Diamond DA40 aircraft.

AIRCRAFT RADIOS

The AUX radio is not supported on this G1000 system configuration for Diamond DA40 aircraft. On the Diamond DA40, if AUX is disabled on the GMA Configuration Page of the PFD, pressing the **AUX** key does not illuminate the corresponding annunciator light.

AIRCRAFT ENTERTAINMENT INPUTS

The Diamond DA40 is not equipped with entertainment channels MUSIC 1 and MUSIC 2.

COCKPIT VOICE RECORDER (CVR)

The Diamond DA40 is not factory-equipped with a cockpit voice recorder.

DUAL PANEL OPERATION

The Diamond DA40 is not configured for dual audio panel installations.




Figure 6B.1.1 G1000 Audio Panel (GMA 1347)



Garmin International, Inc.
1200 East 151st Street
Olathe, KS 66062, U.S.A.
p: 913.397.8200 f: 913.397.8282

Garmin AT, Inc.
2345 Turner Road SE
Salem, OR 97302, U.S.A.
p: 503.391.3411 f: 503.364.2138

Garmin (Europe) Ltd.
Unit 5, The Quadrangle
Abbey Park Industrial Estate
Romsey, SO51 9DL, U.K.
p: 44/0870.8501241 f: 44/0870.8501251

Garmin Corporation
No. 68, Jangshu 2nd Road
Shijr, Taipei County, Taiwan
p: 886/2.2642.9199 f: 886/2.2642.9099

www.garmin.com