

# **G1000**<sup>™</sup>

audio panel pilot's guide supplement for Mooney M20M & M20R

Record of Revisions			
Revision	Date of Revision	<b>Revision Page Range</b>	Description
A	10/18/04	6B-1	Initial release.

This document is only intended to highlight G1000 Audio Panel (GMA 1347) information that is specific to Mooney M20M and M20R aircraft and it supersedes related information presented in the G1000 Audio Panel Pilot's Guide.



**NOTE:** For a description of the GMA 1347 as well as details as to its operation, please see the Garmin G1000 Audio Panel Pilot's Guide.

#### **HEADSET JACKS & KEYED ICS OPERATION**

Mooney aircraft are equipped with four (4) stereo headset jacks (for the pilot, copilot and two passengers).

Keyed ICS operation is not available on Mooney aircraft.

#### TRANSCEIVERS

Mooney aircraft are not factory-equipped with COM3 MIC, COM3 and TEL capability. On Mooney aircraft, if COM3 or TEL is disabled on the GMA Configuration Page of the PFD, pressing the **COM3 MIC**, **COM3**, or **TEL** key, respectively, does not illuminate the corresponding annunciator light.



**NOTE:** The use of split COM (**COM 1/2** key) is not recommended in Mooney aircraft.

## **AIRCRAFT RADIOS**

DME, ADF and AUX radios are not supported on this G1000 system configuration for Mooney aircraft. On Mooney aircraft, if ADF, DME, or AUX is disabled on the GMA Configuration Page of the PFD, pressing the **ADF**, **DME**, or **AUX** key, respectively, does not illuminate the corresponding annunciator light.

#### **AIRCRAFT ENTERTAINMENT INPUTS**

Mooney aircraft are not equipped with entertainment channels MUSIC 1 and MUSIC 2.

## **COCKPIT VOICE RECORDER (CVR)**

Mooney aircraft are not factory-equipped with a cockpit voice recorder.

#### **DUAL PANEL OPERATION**

Mooney aircraft are not configured for dual audio panel installations.




Figure 6B.1.1 G1000 Audio Panel (GMA 1347)

# **GARMIN**

Garmin International, Inc. 1200 East 151st Street Olathe, KS 66062, U.S.A. p: 913.397.8200 f: 913.397.8282

Garmin AT, Inc. 2345 Turner Road SE Salem, OR 97302, U.S.A. p: 503.391.3411 f: 503.364.2138

Garmin (Europe) Ltd. Unit 5, The Quadrangle Abbey Park Industrial Estate Romsey, SO51 9DL, U.K. p: 44/1794.519944 f: 44/1794.519222

Garmin Corporation No. 68, Jangshu 2nd Road Shijr, Taipei County, Taiwan p: 886/2.2642.9199 f: 886/2.2642.9099

www.garmin.com