

HP 15C Emulator Release

Release Date: 2012-11-29

Version information: Rev. 19022

Changes in this version

The product activation was removed and the emulator is now packaged into a multi-lingual installer package. No additional localization was done.

Known Issues in this version

Copy Screen to Clipboard

In Windows XP when copy screen is selected in the menu, the characters on the emulator display are not fully copied (occurs in all skins). This only occurs in Windows XP.

Work around

The end user may take a screenshot using the standard windows print screen button and then manually crop to the desired screen area using a drawing program.

Existing Known Issues

Emulator Skins

When the user selects a new skin, the screen does not render the view properly until the program is restarted. The user will see part of the calculator in the old skin and part in the new skin after a different skin has been selected.

Work around

In order to fix this, the user can either minimize the window and then open it again or close the calculator and reopen.

PSE Functionality in User Program Broken

When a user program uses the pause function for the second time, the display does not update until the end of the program. This issue affects both the emulator and firmware on the hardware. There is no work around.