

MANUAL CHANGES

MANUAL IDENTIFICATION

Model Number: 8447D/E/F
Date Printed: June 1973
Part Number: 08447-90016

This supplement contains important information for correcting manual errors and for adapting the manual to instruments containing improvements made after the printing of the manual.

To use this supplement:

Make all ERRATA corrections

Make all appropriate serial number related changes indicated in the tables below.

Serial Prefix or Number	Make Manual Changes	Serial Prefix or Number	Make Manual Changes
1529A	1		
▶ 1616A	1, 2		

▶ NEW ITEM

CHANGE 1

Change statement under SERIAL NUMBERS on title page to read: This manual applies directly to instruments with the following serial number prefixes:

8447D: 0993A, 1145A, 1529A

8447E: 0993A, 1145A, 1529A

8447F: 0993A, 1145A, 1529A

▶ CHANGE 2

Pages 22 – 24, Tables 4, 5, and 6:

Change A1CR9 to 1884-0073, THYRISTOR-SCR, 28480, 1884-0073.

Add A1R14, 0757-0401, R:FXD MET FLM 100 OHM 1% 1/8W.

Page 29, Figure 14:

Add resistor R14, 100 ohms, from junction of CR8 anode/CR9 gate to ground.

NOTE

Manual change supplements are revised as often as necessary to keep manuals as current and accurate as possible. Hewlett-Packard recommends that you periodically request the latest edition of this supplement. Free copies are available from all HP offices. When requesting copies quote the manual identification information from your supplement, or the model number and print date from the title page of the manual.

25 MAY 1976

1 Page

Printed in U.S.A.

HEWLETT  PACKARD

