

P R O D U C T I O N M E M O

Date: 12 October 1972

TO:

FROM: HP Microwave Division

INSTRUMENT: All 8707A's

SUBJECT: Replacement Fan

The recommended replacement fan in all 8707A's is 3160-0056. This fan is more reliable than the old fan, part number 3160-0097, and is directly interchangeable.

Al Schuettpelz

10/72-4

HEWLETT  PACKARD