



Agilent Technologies

E5061B Network Analyzer Firmware Revision History

Rev. 20140703

Note:

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Agilent representative.

Revision B.03.03 ... Released July 2014

1. Bug Fix: LAN connection failure with Telnet/Socket.

Revision B.03.02 ... Released July 2014

2. Initial version of Windows 7.

Revision A.02.22 ... Released December 2013

1. Bug fixes. The previous reading of marker is output after format change. This occurs only when Display update is turned off.
2. The query of :SENSe:CORRection:COLLect:ECAL:INFormation? is not the same as the E5071C.

Revision A.02.21 ... Released August 2013

1. Minor Enhancement
2. Bug Fix

Revision A.02.12 ... Released October 2012

1. Bug Fix

Revision A.02.11 ... Released August 2012

1. Fixed bugs related to firmware boot up

Revision A.02.09 ... Released June 2012

1. Fixed minor bugs on system recovery issues

Revision A.02.06 ... Released October 2011

1. Added the system error correction ON/OFF capability

Revision A.02.04 ... Released May 2011

1. Added Touch Panel Driver check functions
2. Enhanced Firmware Revision dialog design

Revision A.02.00 ... Released Jan 2011

1. Added RF NA options
2. Added Impedance analysis option for LF-RF NA

3. The return values of VBA query commands on instrument setting has been changed from full spelling to abbreviation for compatibility with other ENA series products.
e.g. LINear -> LIN, PHASe -> PHAS

Revision A.01.14 ... Released Jun 2010

1. Improved of overload protection function
2. Fixed a bug related to the system exit function

Revision A.01.12 ... Released Apr 2010

1. Fixed a bug related to internal ranging operation

Revision A.01.10 ... Released Dec 2009

1. Customer first release

Revision A.09.41 ... Released Sep 2009

1. Demo use only