

E5063A Network Analyzer Firmware/Test Wizard Remote Control Software Revision History

Rev. 20150407

Note:

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

Revision A.02.09 ... Released March 2015

- Bug fixed
 - [Test Wizard A.02.08] Incorrect IFBW after Recall state

Revision A.02.07 ... Released November 2014

- Bug fixed
 - DISP:UPD command does not work at DISP:ENAB OFF mode

Revision A.02.04 ... Released August 2014

- 32 Channel / 16 Trace mode improves measurement efficiency for filter measurements
- U1816A/C SP6T USB switch support provides a lower cost solution for multi-DUT (antenna) measurements
- [Test Wizard] Probe contact check mode for flexible PCBs improves test efficiency
- [Test Wizard] Test range edit operator permission to improve test efficiency
- [Test Wizard] AutoSave image feature for improve test efficiency
- Keysight Technologies rebranding
- Changes on firmware update procedure. The firmware installer file is changed from .msi to .exe.
- Changes on network setup softkeys
- BUG Fix
 - ✧ Detect USB switch without exiting TW
 - ✧ Weird password dialog shows up
 - ✧ "Calibration Extrapolated" message after Ecal

Revision A.01.14 ... Released June 2014

- Soft key localization (Simplified Chinese, Traditional Chinese, Japanese, Korean, Russian)
- Localized Help Supports (Simplified Chinese Help can be loaded by localization package)
- Max Hold Function
- 300k start frequency as preset value

Revision A.01.02 ... Released Jan 2014

- Customer first release