



## E5072A ENA Network Analyzer Firmware Revision History

Rev. 20150408

---

**Note:**

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

---

**Revision B.02.02** ... Released April 2015

Bug Fixes. Analysis > Transform cannot be set to "ON"  
FW crash when Rotate Adapter soft key is pressed

**Revision B.02.00** ... Released December 2014

Rebranded to Keysight  
Changed OS to Win-7

**Revision A.01.14** ... Released October 2014

Minor Enhancement.  
Bug fixes.

**Revision A.01.13** ... Released March 2014

Bug fixes. Receiver Levelling doesn't work properly on Ch2 and above.

**Revision A.01.11** ... Released February 2014

Bug fixes. The previous reading of marker is output after format change. This occurs only when Display update is off.

**Revision A.01.06** ... Released February 2013

Fixed minor bugs.

**Revision A.01.03** ... Released June 2012

Fixed minor bugs on system recovery issues.

**Revision A.01.03** ... Released October 2011

Fixed minor bugs.

**Revision A.01.00** ... Released June 2011

Initial revision