# Agilent 8990B Peak Power Analyzer

### Designed for faster measurement speed and greater measurement accuracy

## **Key specifications**

Model	Description
Frequency range	50 MHz to 40 GHz <sup>1</sup>
Rise time/fall time	5 ns
Video bandwidth	30 MHz (single shot)
	150 MHz (repetitive)
Dynamic range	-35 to +20 dBm
Sampling rate	100 MSa/s (real time), 1 GSa/s (ETS On)
Display	15 in XGA color display with touchscreen capability
Channels	4 channels (2 RF and 2 video)

<sup>1.</sup> Sensor dependent.



The removable hard drive option adds an additional layer of data security for users working in sensitive design environments.



#### Ease of use

Built for ease of use, the 8990B is easy to set, trigger and measure pulse measurements with.


#### High performance

Achieve 5 nanosecond rise time/fall time – the fastest rise time/fall time in the peak power measurement market – when you combine the 8990B with the N1923A or N1924A wideband power sensor.

#### Other features

- · Internal zero and calibration
- 15 pulse characterization measurements, including duty cycle, rise time, pulse top, PRI and PRF
- · Dual screen zoom window
- Backward compatibility with Agilent P-series sensors and U2000 series USB sensors





Remove the need to manually manipulate horizontal markers with the 8990B's automated Pulse Droop measurement.







The Zoom Screen function displays the original signal in the top screen and an enlarged signal trace in the bottom screen.



#### **Quick Fact Sheet**

## **Ordering information**

Options	Description	
Peak power analyzer		
8990B	Peak power analyzer	
Sensors		
N1923A	Wideband power sensor, 50 MHz to 18 GHz	
N1924A	Wideband power sensor, 50 MHz to 40 GHz	

# Standard-shipped accessories for the 8990B peak power analyzer

- · Optical mouse
- · Stylus pen
- · Mini keyboard
- · Calibration certificate
- · 10 Libraries Media Suite
- 50 Ω BNC cable

# Standard-shipped accessories for the N1923A/N1924A wideband power sensor

- · Calibration certificate
- N1923A/N1924A wideband power sensor operating and service guide – English

#### Warranty

- Standard 1-year, return-to-Agilent warranty and service plan
- 3 months for standard-shipped accessories

## **Options**

Options	Description	
Meter		
8990B-800	Standard hard drive, installed	
8990B-801	Removable hard drive, installed	
8990B-U01	With USB host	
8990B-U02	Without USB host	
Sensors		
N1923A/ 24A-105	Fixed cable option length, 1.5 m (5 ft)	
N1923A/ 24A-106	Fixed cable option length, 3 m (10 ft)	
Other accessories		
8990B-1CM	Rackmount kit, 8U full rack	
N6924A	Additional hard drive with image	
Warranty and calibration		
8990B-1A7	0 11 11 11 11 1 10047005	
	Compliant calibration test data - ISO17025, printed	
8990B-A6J	•	
8990B-A6J N1923A/ 24A-1A7	printed  Certificate of compliance calibration - ANSI/	

Refer to Agilent.com website for product details, application notes and other information, visit www.agilent.com/find/peakpoweranalyzer

#### Recommended service options

Additional two years of Return-to-Agilent warranty
Additional two years of Return-to-Agilent calibrations
For more information go to www.agilent.com/find/removealIdoubt

### **Options** (continued)

Options	Description
Documentation	
8990B-0BF	English language programming guide, printed
8990B-0BK	English language user and programming guide, printed
8990B-0BW	English language service guide, printed
8990B-ABJ	Japanese user guide and English programming guide, printed
N1923A/24A-ABJ	Japan, Japanese user guide, printed
N1923A/24A-0B1	English language user guide, printed
N1923A/24A-0BN	English language service guide, printed



The Agilent N1923A and N1924A wideband power sensors.

