

Special Notice

If your N5242A PNA-X Network Analyzer has a serial number below MY/SG/US 49000000, please check the part number of the A12 SPAM board. If it is N5240-60041, replace it with the enclosed N5264-60005 SPAM board, provided free of charge. The new N5264-60005 SPAM board allows for greater data throughput which is necessary for option 118.

Replacement instructions, along with the necessary adjustments and other procedures, are located in the N5242A PNA-X Service Guide chapter seven section titled, "Removing and Replacing the A4-A13 Boards."

To view the Service Guide online, use the following steps:

1. Go to <http://www.agilent.com>.
2. Enter your PNA model number (N5242A) in the Search box and click **Search**.
3. Look in the left column for the heading **Refine Your Results by Type of Content**, and click on **Manuals**.
4. In the left column, click on **Service Manual**.
5. In the right column, click on the title/hyperlink for the N5242A Service Guide PDF.

For the latest PNA firmware and service information, please refer to the Agilent PNA Series Service & Support Home Page at <http://na.tm.agilent.com/pna>.



Agilent Document Number: N5242-90014

Print Date: July 2009

© Agilent Technologies, Inc. 2009