

## S E R V I C E N O T E

SUPERSEDES: None

**4155A Semiconductor Parameter Analyzer**

Serial Numbers: JP10A00101 / JP10A00117

**Push button keys stick in the front panel****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

Part No.	Qty.	Description
04155-40003	1	Front Keys
04155-65101	1	Front Panel

**Situation:**

The push button keys may stick in the front panel, or may not stick out enough from the front panel.

**Solution/Action:**

Replace the Front Keys and Front Panel.

DATE: October 1994

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
<b>MODIFICATION RECOMMENDED</b>					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 1.0 Hour		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: October 1997		
AUTHOR: MN	ENTITY: 3301	ADDITIONAL INFORMATION:			