# S E R V I C E N O T E

SUPERSEDES: None

## **HP 4156A Precision Semiconductor Parameter Analyzer**

**Serial Numbers:** 0000A00000 / 9999Z99999

## Flexible Disk Drive Discontinuance and Replacement

**Duplicate Service Notes:** 4155A-08

To Be Performed By: HP-Qualified Personnel

Parts Required:

See test.

**Situation:** 

The flexible disk drive (HP P/N 0950-2348) for the HP 4156A was discontinued.

DATE: July 1997

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:	
МО	3300		

© 1997 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note 4156A-09

### **Solution / Action:**

The replacement of 0950-2348 is 0950-3108. The HP 4156As with the following serial numbers are shipped with the new FDD (0950-3108):

HP 4156A: JP10A01033 and above

The FDD cable and the FDD cover were also changed to fit the new FDD:

	Existing	Replacement	
FDD	0950-2348	0950-3108	
FDD Cable	04155-61615	04155-61620	
FDD Cover	04155-04003	04155-04030	

If an old FDD (0950-2348) needs to be replaced and 0950-2348 is no longer supplied, order the new FDD, new FDD cable, and new FDD cover.