|    |  |   |   |   |   |   |            | 41       | 56B-   | -06 |
|----|--|---|---|---|---|---|------------|----------|--------|-----|
| S  | Е  | R | V | Ι | С | Е | Ν          | 0        | Т      | Е   |
|    |  |   |   |   |   |   | SUPERSE    | DES: Non | le     |     |
| 4  | 4156B Semiconductor Parametric Analyzer  |   |   |   |   |   |            |          |        |     |
| Se | Serial Numbers: See below.   |   |   |   |   |   |            |          |        |     |
| F  | Flexible Disk Drive Change   |   |   |   |   |   |            |          |        |     |
| D  | Duplicate Service Notes:   |   |   |   |   |   |            |          |        |     |
|    | 4155B-06 Serial Numbers: 0000A00000/9999Z99999   4156B-06 Serial Numbers: 0000A00000/9999Z999999 |   |   |   |   |   |            |          |        |     |
| Т  | To Be Performed By: Agilent-Qualified Personnel  |   |   |   |   |   |            |          |        |     |
| P  | Parts Required: See text.  |   |   |   |   |   |            |          |        |     |
| Si | ituation:  |   |   |   |   |   |            |          |        |     |
| T  | The flexible disk drive (P/N 0950-3109) for the 4155B, 4156B was changed.                        |   |   |   |   |   |            |          |        |     |
|    |  |   |   |   |   |   |            |          |        |     |
|    |  |   |   |   |   |   |            |          |        |     |
|    |  |   |   |   |   |   |            |          | Contin | ued |
|    |  |   |   |   |   |   | DATE: Janı | ary 1999 | •      |     |

## ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICA                  | TION:     |                         |
|--|-----------|-------------------------|
|  | INFORMATI | ON ONLY                 |
| AUTHOR:                                  | ENTITY:   | ADDITIONAL INFORMATION: |
| TW                                       | 3300      |                         |
|  |           |                         |
| © 1999 AGILENT TECH<br>PRINTED IN U.S.A. | HNOLOGIES | Agilent Technologies    |

1 of 2

## Solution / Action:

The replacement of 0950-3109 is 0950-2782. The 4155Bs, 4156Bs with the following serial numbers are shipped with the new FDD (0950-2782):

4155B: JP10E00303 and above 4156B: JP10E00342 and above

The FDD cover, the FDD cable, and the Front panel were also changed to fit the new FDD:

## 4155B:

|             | 0000A00000/JP10E00302 | JP10E00303/9999Z99999 |  |
|-------------|-----------------------|-----------------------|--|
| FDD         | 0950-3109             | 0950-2782             |  |
| FDD Cover   | 04155-04053           | 04155-04056           |  |
| FDD Cable   | 04155-61620           | 04155-61615           |  |
| Front Panel | 04155-65141           | 04155-65151           |  |

## 4156B:

|             | 0000A00000/JP10E00341 | JP10E00342/9999Z99999 |  |
|-------------|-----------------------|-----------------------|--|
| FDD         | 0950-3109             | 0950-2782             |  |
| FDD Cover   | 04155-04053           | 04155-04056           |  |
| FDD Cable   | 04155-61620           | 04155-61615           |  |
| Front Panel | 04155-65141           | 04155-65151           |  |