# S E R V I C E N O T E

SUPERSEDES: None

## 4268A 120Hz/1kHz Capacitance Meter

**Serial Numbers:** 0000A00000 / 9999Z99999

Repair strategy for special option S5V.

To Be Performed By: Agilent-Qualified Personnel

#### **Situation:**

Special option S5V is to set the voltage setting of Handler I/F and Scanner I/F to +5V. When we ship 4268A with option S5V to the customer, we attach label of "S5V" to rear panel of the product. When you receive 4268A with option S5V, refer to the following solution/action.

Continued

DATE: August 2000

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:  INFORMATION ONLY		
AUTHOR: TK	ENTITY: 3355	ADDITIONAL INFORMATION:

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 4268A-02

## **Solution / Action:**

When you replace A1 board for option S5V, set bit switches (S1,S2,S3) on A1 board as follows.

(S2) for Handler

ON

1 o

2 o

3 o

4 o

(S1) for Scanner

ON

1 o

2 o

3 o

4 o

5 o

6 o 7 o

8 o

(S3) for Scanner

ON

1 o

2 o

3 o

4 o