S E R V I C E N O T E

SUPERSEDES: None

4278A 1kHz/1MHz Capacitance Meter

Serial Numbers: 0000A00000 / 9999Z99999

Replacement of GPIB board

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N Description Quantity 04278-66520 or 04284-66520 GPIB board 1

(The same board as the one installed in the equipment)

Situation:

GPIB board (P/N 04278-66520) is replaced with 04284-66520.

Solution / Action: Confirm the P/N of the installed GPIB board before exchanging the GPIB board. The GPIB board has black and red extractors. The P/N is printed near the black extractor.

DATE: January 1999

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | |
|------------------------------|----------|-------------------------|
| | INFORMAT | TON ONLY |
| AUTHOR: | ENTITY: | ADDITIONAL INFORMATION: |
| НМ | 3355 | |

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

