

4280A-09

S E R V I C E N O T E

SUPERSEDES: None

HP 4280A 1MHz C Meter/C-V Plotter

Serial Numbers: 0000A00000 / 9999Z99999

Duplicate Service Notes:

4140B-16
4084A/B-01
4086A-01

Recommended replacement for fan assembly

To Be Performed By: HP-qualified personnel

Parts Required:

HP P/N	Qty	Description
04140-65100	1	Fan Assembly

Situation:

Currently, service manuals of the above products show part number 3160-0273 as the replaceable part number for the fan. However, when a fan fails, it is necessary to re-verify pins and connectors on the new fan to connect the fan cable to the instrument. This is because part number 3160-0273 has no connectors.

Continued

DATE: 14 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
IT	3301	

© 1991 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.



Solution/Action:

We recommend using the fan assembly of HP part number 04140-65100 to repair fans on the above products. This fan assembly contains the necessary pins and connectors, and repair time is reduced.