4287A-09

# <u>SERVICE NOTE</u>

Supersedes: None

## 4287A RF LCR Meter

Serial Numbers: MY43300401 or later

While replacing A20 ATX Digital Mother Board, use the new part-numbers

Parts Required: See Solution/Action

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

## **INFORMATION ONLY**

AUTHOR: jm PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.

**Agilent Technologies** 

April 24, 2007

Page 2 of 2 4287A-09

#### **Situation:**


Part-numbers for A20 ATX Digital Mother Board and its screw have been changed.

#### **Solution/Action:**

Old P/N New P/N Description

0960-2372 04287-62003 A20 ATX Digital Mother Board

0515-1250 0515-0430 Screw M3



- End of Document -