

S E R V I C E N O T E

SUPERSEDES: None

**4073A Ultra Advanced Parametric Tester**

**Serial Numbers:**

- E3101A      JP20D00301/JP99Z99999
- E3102A      JP00A00000/JP99Z99999
- E3102L      JP00A00000/JP99Z99999
- E3103A      JP00A00000/JP99Z99999

**Rear door may rub off paint coat of PDU main switch.**

**Duplicate Service Notes:**

- E3101A-15
- E3102A-03
- E3103A-02

**To Be Performed By:** Agilent-Qualified Personnel

**Parts Required:** None

**Situation:**

If the floor of 4070 installation site is uneven and the cabinet is distorted, the rear door may rub off the paint coat of PDU main switch.

**Solution / Action:**

Raise the rear left corner (rear door hinge side) by lowering the leveling foot.

DATE: January 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR: SY	ENTITY: 3300	ADDITIONAL INFORMATION:

