

S E R V I C E N O T E

SUPERSEDES: 35670A-04

35670A 2 or 4 Channel Dynamic Signal Analyzer**Serial Numbers:** 0000A00000 / 9999Z99999**Recommended Replacement Floppy Drive and Dust Cover****Situation:**

The 3.5 inch floppy drive and its associated dust cover have been replaced with a newer version drive. If the original drive contains a plastic dust cover on the rear portion, this dust cover can be discarded, since the new floppy drive mechanism does not need this cover.

Solution/Action:

A new drive part number has been setup to replace the floppy drive (A100).

The new part number is:

A100 Floppy Drive 0950-3282 (old pn was 0950-2990)

DATE: August 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

MJL

ENTITY:

MSD

ADDITIONAL INFORMATION:

