S E R V I C E N O T E

SUPERSEDES: None

35670A 2 or 4 Channel Dynamic Signal Analyzer

Serial Numbers: 0000A00000 / 9999Z99999

35670A Replacement Lithium Battery

Parts Required: None

Situation:

The Lithium Battery (A8B200) on the A8 assembly has been replaced with a new part number.

Solution/Action:

A new part number has been setup to replace the Lithium Battery (B200) located on the A8 assembly.

A8B200 Lithium Battery 1420-0277

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICAT	TION:	
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
MJL	A100	

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

