S E R V I C E N O T E

SUPERSEDES: None

3569A Real-Time Frequency Analyzer

Serial Numbers: 0000A00000/9999Z99999

3569A Replacement Power Pack for US and Canada Only

Parts Required: None

Situation:

The power supply pack listed in the manuals for use in the United States and Canada is 82241-60001. This part is obsolete and no longer available.

Solution/Action:

A new part had been setup to replace this power supply pack for use in the USA and Canada. The new part number for this replacement power supply pack is 5183-2823.

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
MJL	A100	USA and Canada Only

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

