

3577A-16

S E R V I C E N O T E

SUPERSEDES

HP 3577A Network Analyzer

Serial Numbers: 0000A00000/3001A14520

A1 Receiver board replaced by kit

Situation:

The receiver board (03577-66501) in the HP3577A has been redesigned to use surface mount parts. This new board has been renumbered 03577-66509. The electrical lengths between A1 and A9 are slightly different, which could cause a phase match problem. Therefore, the cable from the front panel to the receiver must be replaced to compensate for the electrical length when an A1 is replaced with an A9.

Solution:

When replacing 03577-66501, order kit part number 03577-84405. This kit will include the new receiver (03577-66509) and the new cable (03577-61627). Both parts must be installed to insure proper phase match between the new A9 board and the old A1 board(s).

DATE: 24 September 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

DWH

ENTITY:

A100

ADDITIONAL INFORMATION:

See Service Note 3577B-05

© 1993 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

