## S E R V I C E N O T E

SUPERSEDES: None

## **5345A Electronic Counter**

**Serial Numbers:** 0000A00000 / 3103A13750

The 5345A Electronic Counter has been experiencing intermittent power-up display problems. We have been able to correct the problem by replacing A13 U7 (part number 1820-1416) with a different vendor. The current part is used in many Agilent products, which are not experiencing problems with this part.

To resolve this problem for the 5345A, we have changed to a new vendor and changed the part number. The new part number is 1821-0734.

DATE: 10 February 1993

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 0.5 Hour
LOCATION CATEGORY:	<ul><li>■ CUSTOMER INSTALLABLE</li><li>■ ON-SITE</li><li>■ SERVICE CENTER</li></ul>	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: February 1995
AUTHOR: JWE	ENTITY: 0200	ADDITIONAL INFORMATION:

© 1993 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

