

# 5381A-05

## S E R V I C E N O T E

SUPERSEDES: None

### HP 5381A Frequency Counter

#### Replacing the A1CR1 Diode, 1906-0028

**Serial Numbers:** 0000A00000 / 9999A99999

**To Be Performed By:** Customer / HP-Qualified Personnel

**Parts Required:** HP Part No. 1906-0096

**Tools Required:**

Soldering iron  
Needle-nosed pliers

The 1906-0028 DIODE - MULT. FULL WAVE BRIDGE RECTIFIER is no longer available. For service replacement of the A1CR1 diode, please order HP Part No. 1906-0096. No further modifications are required.

DATE: 16 September 1992

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

## INFORMATION ONLY

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
AI	0200	

© 1992 HEWLETT-PACKARD COMPANY  
PRINTED IN U.S.A.

