

DSO80604B-06

S E R V I C E N O T E

Supersedes:
NONE

DSO80604B 6GHz 4 Channel Oscilloscope
Serial Numbers: MY46000402 MY46001917

The DSO80000B in the serial number range above possibly has a contamination internal to the power supply. The failure symptom is the scope will suddenly shut down intermittently. This is not a safety concern for any reason. The purpose of the service note is to approve this repair to be performed under warranty for a 3 year warranty period. After the 3 years from shipment if the power supply was to fail then this is not due to the contamination issue, it would be considered a normal failure.

Parts Required:

P/N	Description	Qty.
54857-62601	SUBASSEMBLY POWER SUPPLY	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: MR PRODUCT LINE: PL1A
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



November 19, 2007

Situation:

If the instrument intermittently shuts down and the power supply is suspected to be bad it could be due to contamination internal to the power supply..

Solution/Action:

Replace power supply.