A MODIFICATION ONLY - DOES NOT COMMUNICATE

DSO80804A-01					
N	0	Τ	Ε		

Supersedes: None

DSO80804A Infiniium Oscilloscope- 40 GSa, 4 Ch, 8 GHz

Serial Numbers: [0000A00000 / 9999Z99999]

The service manual will not be available for this product until fall of 2005. Use this service note for changes to the performance test section for the service manual used on the other products in this family.

Parts Required:	D ' ('	04	
P/N	Description	Qty.	
None			

ADMINISTRATIVE INFORMATION

SERVICE NOTE	CLASSIFICATION:			
INFORMATION ONLY				
AUTHOR: KO	PRODUCT LINE: 1A			
ADDITIONAL IN	FORMATION:			

© AGILENT TECHNOLOGIES, INC. 2005 PRINTED IN U.S.A.



April 22, 2005

Page 2 of 2 DSO80804A-01

Situation:

The service manual for the DSO80804A will not be available until fall of 2005. Until then service centers and customers can use the performance test section of the 54855-97000 service manual written for the rest of the products in the family. The only difference between the DSO80804A and the rest of the family is that the DSO80804A has a lower bandwidth of 8 GHz.

Solution/Action:

Make the following changes to Chapter 3: Testing Performance.

Page 3-16 - Add DSO80804A 8 GHz to the Specification table

Page 3-21 - Add DSO80804A 8 GHz and 100 ps/div to the table in step 11

Page 3-26 - Add DSO80804A = 8 GHz to the top of the table on that page

For product specifications refer to the Infiniium 80000 Series Oscilloscopes InfiniiMax II Series Probes at www.agilent.com or a direct line is http://cp.literature.agilent.com/litweb/pdf/5989-1487EN.pdf