DSO81204B-06

<u>SERVICE NOTE</u>

Supersedes: NONE

DSO81204B 12GHz 4 Channel Oscilloscope Serial Numbers: MY46000416 MY46001904

The DSO80000B in the serial number range above possibly has a contamination internal to the power supply. The failure symptom is the scope will suddenly shut down intermittently. This is not a safety concern for any reason. The purpose of the service note is to approve this repair to be performed under warranty for a 3 year warranty period. After the 3 years from shipment if the power supply was to fail then this is not due to the contamination issue, it would be considered a normal failure.

Parts Required:

P/N Description Qty.

54857-62601 SUBASSEMBLY POWER SUPPLY 1

ADMINISTRATIVE INFORMATION

INFORMATION ONLY

AUTHOR: MR PRODUCT LINE: PL1A

SERVICE NOTE CLASSIFICATION:

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.



Page 2 of 2 DSO81204B-06

Situation:

If the instrument intermittently shuts down and the power supply is suspected to be bad it could be due to contamination internal to the power supply..

Solution/Action:

Replace power supply.