

S E R V I C E N O T E

SUPERSEDES: None

6011A Autoranging DC Switching Power Supply

Serial Number: See Below

Installing New Fan

Duplicate Service Notes:

6010A-10 0000A00000/US37110121
 6011A-11 0000A00000/US35460131
 6012B-09 0000A00000/US35430201
 6015A-06 0000A00000/US37050106
 6030A-19 0000A00000/US37020171
 6031A-21 0000A00000/US35430221
 6032A-20 0000A00000/US35420521
 6035A-09 0000A00000/US37020151

To Be Performed By: Agilent-Qualified Personnel

Situation:

Old fan p/n 3160-0097 is being replaced by p/n 3160-0899.

Solution / Action:

When replacing the old fan with the new one, make sure the direction of air flow from the fan is going into the unit.

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GS	2100	