

S E R V I C E N O T E

SUPERSEDES: None

**6015A Autoranging DC Switching Power Supply**

**Serial Number:** See Below

**Installing New Fan**

**Duplicate Service Notes:**

- 6010A-10 0000A00000/US37110121
- 6011A-11 0000A00000/US35460131
- 6012B-09 0000A00000/US35430201
- 6015A-06 0000A00000/US37050106
- 6030A-19 0000A00000/US37020171
- 6031A-21 0000A00000/US35430221
- 6032A-20 0000A00000/US35420521
- 6035A-09 0000A00000/US37020151

**To Be Performed By:** Agilent-Qualified Personnel

**Situation:**

Old fan p/n 3160-0097 is being replaced by p/n 3160-0899.

**Solution / Action:**

When replacing the old fan with the new one, make sure the direction of air flow from the fan is going into the unit.

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GS	2100	