

S E R V I C E N O T E

SUPERSEDES: NONE

6033A System DC Power Supply

Serial Numbers: 0000A00000 / 9999A99999

Rotary Pulse Generator / Knob Replacement**Duplicate Service Notes:**

6033A-11

6038A-09

To Be Performed By: Agilent-Qualified Personnel**Parts Required:**

Part No.	Description
06033-60008	RPG Assembly
01650-47401	Knob

Situation:

Improve manufacturability and consolidate RPG parts usage.

Solution/Action:

RPG part number 06033-60008 is replacing RPG part number 06033-60007 and is backward compatible. Replacing part number 06033-60007 with part number 06033-60008 requires push-on knob part number 01650-47401.

This service note is for part change information only. RPG pn 06033-60007 should only be replaced on failure.

DATE: 10 June 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
BH	2100	