

S E R V I C E N O T E

SUPERSEDES: NONE

**6038A System DC Power Supply**

**Serial Numbers:** 0000A00000 / 9999A99999

**Rotary Pulse Generator / Knob Replacement**

**Duplicate Service Notes:**

6033A-11  
6038A-09

**To Be Performed By:** Agilent-Qualified Personnel

**Parts Required:**

Part No.	Description
06033-60008	RPG Assembly
01650-47401	Knob

**Situation:**

Improve manufacturability and consolidate RPG parts usage.

**Solution/Action:**

RPG part number 06033-60008 is replacing RPG part number 06033-60007 and is backward compatible. Replacing part number 06033-60007 with part number 06033-60008 requires push-on knob part number 01650-47401.

This service note is for part change information only. RPG pn 06033-60007 should only be replaced on failure.

DATE: 10 June 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
BH	2100	