

S E R V I C E N O T E

SUPERSEDES: None

6571A DC Power Supply**Serial Numbers:** 0000A00000 / 3436A00143**Downprogramming FETs Q901 no longer has an isolated package.****To Be Performed By:** HP-Qualified Personnel**Parts Required:** Kit, Dwnprgmr-Svc, 5063-3418**Situation:**

The original part, HP part number 1855-0834 has been discontinued by the manufacturer and the replacement part does not have an isolated package. Therefore, it can not be mounted directly to the heat sink.

Solution / Action:

If the original part fails it may be replaced by the service kit 5063-3418. The kit consists of a new FET, 1855-0874, and an insulator, 0340-1507.

DATE: March 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

DF

ENTITY:

2100

ADDITIONAL INFORMATION: