

## S E R V I C E N O T E

SUPERSEDES: NONE

**6621A Multiple Output System DC Power Supply**

Serial Numbers: 0000A00000 / 3150A01570

**Replacement of AC input module with new design requires replacement of associated cables.****Duplicate Service Notes:**

6621A-07  
 6622A-05  
 6623A-09  
 6624A-07  
 6625A-03  
 6626A-03  
 6627A-01  
 6628A-03  
 6629A-03

**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

<b>Part No.</b>	<b>Description</b>
9135-0419	Line module
5060-3441	Cable assembly
5060-3442	Cable assembly
5060-3443	Cable assembly

*Continued*

DATE: 06 June 1994

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:

DF

ENTITY:

2100

ADDITIONAL INFORMATION:

**Situation:**

The AC input module, pn 9135-0306, has been replaced with a new design and the new part is incompatible with the old cables.

**Solution/Action:**

When replacing the line module also replace the three cables, W2, W3 and W4, to the module. Capacitor, CO (0.22uF 250V) is built into the new module so the external cap is not used. The unit should be tested to insure proper operation at the four line voltage options.