6628A-07

S E		R	V		С	Е		Ν	0	Т	Е
							SUPEF	RSEDE	S: NONI	E	
6628A I	DC P	ower	Supply	7							
Serial Nu	mbers	<b>s:</b> 0000 <i>A</i>	400000 /	9999 <i>A</i>	\$99999						
The rep nators ( the orig	2326,	, Q327	and Q		-			•		-	
Duplicate	Servi	ice Note	es:								
6621A-10		Serial Numbers: 0000A00000 / 9999A99999									
6622A-08		Serial Numbers: 0000A00000 / 9999A99999									
6623A-12		Serial Numbers: 0000A00000 / 9999A99999									
6625A-07	' ;	Serial Numbers: 0000A00000 / 9999A99999									
6626A-07	· .	Serial N	lumbers:	0000A	00000 /	9999A9	99999				
6628A-07		Serial N	Numbers:	0000A	00000 /	9999A9	99999				
6629A-07		Serial N	Numbers:	0000A	00000 /	9999A9	99999				
To Be Per	rforme	ed By: A	Agilent-Ç	Qualifi¢	ed Person	nnel					
Parts Req	luired	: Transi	stor 1853	3-0754							
									C	Continued	
							DATE: 、	June 19	96		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	ATION:						
INFORMATION ONLY							
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:					
DF	2100						

© 1996 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



## Situation:

Transistor 1853-0423 is no longer available from the manufacturer and the replacement part has a different lead configuration.

## Solution/Action:

If the 1853-0423 fails it may be replaced with a 1853-0754. The original part had the base in the center and the collector on the right side (viewed with the mounting plate away from the viewer and the leads facing down). The new part has the base and collector leads reversed. The leads must be bent and the part mounted as in the attached figure.

