

## S E R V I C E N O T E

SUPERSEDES: NONE

**6633B DC Source**

Serial Numbers: See Below

**Low range current readback out of spec.****Duplicate Service Notes:**

66312A-01 Serial Numbers: US36312080 / US37442212  
 66332A-01 Serial Numbers: US36320632 / US36320653  
 6612B-01 Serial Numbers: US36340716 / US36340740  
 6632B-01 Serial Numbers: US36351903 / US36351964  
 6633B-01 Serial Numbers: US36390490 / US36390503  
 6634B-01 Serial Numbers: US36380375 / US36380389

To Be Performed By: Agilent-Qualified Personnel

**Situation:**

Units between the given serial number range might have had their low current range readback mis calibrated.

**Solution / Action:**

Should any units be returned with a current readback problem, recalibrate the low range current readback as described in the service manual.

DATE: December 1997

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: BM	ENTITY: 2100	AGILENT RESPONSIBLE UNTIL:	December 2001
		ADDITIONAL INFORMATION:	