S E R V I C E N O T E

SUPERSEDES: 6634B-04

6634B Mobile Communications DC Source

Serial Number: see below

6634B Current Programming Accuracy At Zero Amps

Duplicate Service Notes:

US00000000 / US00000000
US00000000 / US00000000

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required: None

Continued

DATE: December 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY		
AUTHOR: BM	ENTITY: 2100	ADDITIONAL INFORMATION:

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 6634B-04

Situation:

The Current Programming Accuracy is out of spec when programmed between Zero and 0.03% of Full Scale Current.

Solution / Action:

The new "Programming Accuracy" spec when programmed between Zero and 0.03% of Full Scale Current is the following:

```
3.32mA
6611C =
6612C =
              1.53mA
6613C =
              1.01mA
6614C =
              0.631mA
66309B,D =
              2.13mA
              2.13mA
66111A =
66311A,B,D =
              2.13mA
66312A =
              1.53mA
6631B =
              6.63mA
66332A =
              3.32mA
6632B =
              3.32mA
6633B =
              1.53mA
6634B =
              0.76mA
```

Note:

The New Spec = 1 LSB + The Old Spec

```
These units use a 12 Bit DAC; 2^12 = 4,096 Total Counts
The No.of DAC Counts actually used = 3,774
1 LSB(mA)= Full Scale Current/3,774
LSB% = 1/3,774 \times 100\% = \sim 0.03\%
```