

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

6641A-02A

S E R V I C E N O T E

Supersedes:
6641A-02

6641A System DC Power Supply

Serial Numbers: 0000A00000 / 3619A00406

Keypad board, Optical Encoders and Knobs have been changed and are not interchangeable with the old ones.

Parts Required:

P/N	Description	Qty.
5060-3400	Keypad PCA	1
0960-0912	Optical Encoders G1 and G2	2
0370-3238	Knob	2

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DF / RJM PRODUCT LINE: 33

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



June 3, 2002

Situation:

The original Optical encoders have been replaced, and the new encoder is not interchangeable with the older part either mechanically or electrically. This required changes to the front panel firmware, the keypad PC board and the knobs.

Solution/Action:

For serial numbers 3619A00406 and above use the new parts. If the older parts fail in the earlier serial numbers and parts are not available then all the parts listed above must be replaced as a set.

The encoders are part of the new keyboard assembly so they would not need to be ordered separately.

The keyboard contains the EEPROM initialization and calibration data. After replacing the board it must be re-initialized and calibrated / aligned.