

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

6655A-06B

S E R V I C E N O T E

Supersedes:
6655A-06A

6655A 500W General Purpose System Power Supply

Serial Numbers: 3619A-00801 / 9999Z99999

Front Panel Parts List

Situation:

When damage occurs to the front panel portion of the power supply, several replacement parts may be required to repair the instrument.

Solution:

This is a parts list for convenience that lists the commonly replaced front panel parts.

Units with earlier serial numbers, that need new optical encoders must also order a new “**Tested Keypad PCA**” p/n **5060-3400**, which includes 2 knobs.

5064-0125 / 5064-0126 ASSY-FR PNL, SERVICE KIT is Obsolete, and is no longer available.

Front Panel Parts Required:

<u>Part Number</u>	<u>Quantity</u>	<u>Description</u>
0370-3238	2	KNOB 6mm
0515-0374	2	SCR-MACHINE
0515-2535	1	SCREW-METRIC
0960-0912	2	ENCODER-ROTARY
1000-0842	1	WINDOW
5001-0539	2	TRIM SIDES, FRONT GRAY
5001-6748	1	FRONT PANEL (Overlay)

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: RJM PRODUCT LINE: 33

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



June 28, 2002

5040-1735	1	KEYPAD
06655-80001	1	NAMEPLATE
5040-1703	1	FRONT FRAME